

Abbreviated Bridge Condition Report



For

REGION / DISTRICT: 1 / 1

ROUTE: F.A.P. 360 (Kirk Road)

COUNTY: Kane County

STRUCTURE NUMBER: 045-3096

LOCATION: *Kirk Road over Union Pacific RR & Reed Road*

PREPARED BY: Hampton, Lenzini & Renwick Inc. and
Strand Associates, Inc.®

DATE INSPECTED: January 16, 2014

PROPOSED LETTING DATE: unknown



Hampton, Lenzini and Renwick, Inc.
Civil Engineers, Structural Engineers & Land Surveyors
Springfield, IL
217-546-3400



STRAND ASSOCIATES, INC.®
IDFPR No. 184-001273
1170 South Houbolt Road
Joliet, IL 60431
www.strand.com

Table of Contents

| Item: | Page: |
|--|--------------|
| I. Geographical and Administrative Data | 3 |
| II. Physical Description of Structure | 3 |
| III. Field Inspection and Physical Evaluation | 4 |
| IV. Potential Scope of Work Determination and Analysis | 6 |
| V. Discussion and Recommended Scope of Work | 7 |

Attachments:

- A. Roadway Classification Map
- B. IDOT Master Structure Report
- C. Bridge Inspection Report
- D. Top and Bottom of Deck Condition Surveys
- E. Substructure Condition Surveys
- F. Cost Estimates
- G. Proposed Structure
- H. Staging Sketch
- I. Structure Photographs
- J. Existing and Proposed Roadway Cross Sections
- K. Abbreviated Existing Plans

I. Geographical and Administrative Data

Structure Number: 045-3096
County: Kane
Route Carried: FAU Route 2 (Kirk Road)
Feature Crossed: Union Pacific Railroad and Reed Road
Section: 21-000192-04-BR
Station: 13+50.11
Roadway Classification: Other Principal Arterial
Design/Posted Speed:
ADT (current/design): 25,900/33,048 (2010/2032)
ADTT (current/design): 1,813/2,313 (7 percent)
DHV:
Inventory Rating HS: 20.0 (IDOT Master Structure Report)
Operating Rating HS: 27.3 (IDOT Master Structure Report)
Sufficiency Rating: 66.0

Construction / Reconstruction / Repair History:

Year Constructed: 1974—Original construction
Year/s Reconstructed: 1987—Concrete deck overlay
2003—New joints, drain extensions, and deck, parapet, and steel repairs
2013—Deck repairs

II. Physical Description of Structure

Superstructure Type: Steel girder (I-section)

Substructure Type:

Abutments: reinforced concrete spill through
Piers: reinforced concrete multi-column

Length and Width: 1,376'-2" back to back of abutments; 62'-0" out-to-out of deck; 55'-6" roadway width (plus 3'-0" raised concrete median)

Span Arrangement and Lengths: 4-units totaling 18-spans on a curved/tangent alignment with super-elevation transition

Skew: 0°

Existing Wearing Surface Type and Thickness: Concrete wearing surface—3"

Existing Horizontal and Vertical Alignment:

Horizontal—a horizontal curve is present at the north end of the structure
Vertical—the bridge sits in a section with a crest and sag vertical curve

Utilities and Attachments Present: One–2" utility pipe is located on the east side of the bridge in the first interior bay of the deck from that end. Two additional utility pipes are located on the west side of the bridge, a 2 1/2" pipe is attached to the outside of the fascia beam and 1 3/4" pipe is suspended from the deck in the first interior bay from that end.

III. Field Inspection and Physical Evaluation

Superstructure:

Deck: The deck was originally constructed in 1974 with a 7.5" thickness. In 1987 the deck had a concrete overlay placed on it. The overlay consisted of milling off the top 2" of concrete and replacing it with 3" of concrete overlay to make for a new total concrete thickness of 8.5". An additional deck patching contract was completed in 2013. The deck is currently in **poor condition** overall.

Top of Deck–The deck overlay is heavily delaminated with map cracking and numerous open cracks present. A few small areas are spalled and numerous locations have concrete and temporary bituminous patches in place. The total top of deck area is approximately 76,260 square feet (sq. ft.) (minus median and parapets). An estimated 17,300 sq. ft., or 22.7 percent of this area is delaminated, spalled or patched. (See the Top of Deck Survey and photos 18 to 26)

Bottom of Deck–The bottom of the deck has numerous areas with cracking, leaching, delaminations and spalls present. There are three longitudinal construction joints in the deck, one in each of the outer bays and one in the center bay. It is estimated the concrete along these joints is delaminated or spalled over an area approximately 1' wide for 35 percent of the length of each of the outer construction joints. The total bottom of deck area is approximately 80,380 sq. ft. (minus the area beneath the parapets). An estimated 5,200 sq. ft., or 6.5 percent minimum of this area is delaminated, spalled or is heavily cracked and leaching. (See the Bottom of Deck Survey and photos 28 to 35)

Parapets and Bridge Lighting–The parapet is a GM type with an aluminum handrail. Large areas of the inside face of the concrete parapet are cracked with delaminations and spalls present. Concrete repairs have been made in many locations to this portion of the parapet in the past; however, many of these repairs are failing. It is estimated approximately 35 percent of the inside face of each parapet is damaged, or 2,400 sq. ft. The deck located beneath the parapets is heavily damaged. It is estimated 50 percent of the length of the east and 30 percent of the west deck area located beneath the parapets is damaged over a width of 1.5'. This is equal to approximately 1,650 sq. ft. (2.1 percent) of additional concrete damage to the bottom of the deck area. (see photos 14 to 17 and 28)

The aluminum handrail anchorage is damaged due to impact on the west side of Span-14.

The parapet mounted light poles are missing or damaged in a number of locations. Light poles are missing on the east side of Span-7 and the west side of Span-14 (see photo 27). There is impact damage to the light poles located on the east side of Span-3, west side of Span-5, west side of Span-10 and the east side of Span-16. The concrete at the base of the light pole on the east side of Span-12 is spalled, causing reduced bearing area.

Joints: The bridge has transverse joints located at the North and South Abutments as well as Piers 3, 8, and 13.

Abutment Transverse Joints—The original joint seals at both abutments have been replaced with silicon joint seals. These seals have failed at both abutments allowing large amounts of runoff from the deck to pass through to the beams and substructure elements located below (see photos 9 and 13).

Pier Transverse Joints—The transverse joints at Piers 3, 8, and 13 are currently modular type joints. They are in satisfactory condition with only minor damage and leakage noted (see photos 10 to 12).

Beams: The bridge girders consist of non-composite weathering steel W36 sections. They are in **satisfactory condition** with only minor problems noted (see photos 28 to 35).

Some beam ends located below the transverse deck joints have suffered minor section loss to the web and bottom flange. These areas were originally unpainted. Minor pitting and section loss occurred on the steel in these areas once the deck joints began to fail and allowed roadway drainage to pass through to the beams. The beam ends and bearings located below the joints were painted in 2003 to prevent further corrosion. This paint is beginning to fail at a few locations. The section loss at these locations is approximately 1/16" at the most (see photos 39 and 40).

Minor corrosion with no significant section loss has also occurred on the bottom flanges at a few locations adjacent to deck drain down spouts that do not extend sufficiently far below the bottom of the beams. The section loss at these locations is approximately 1/16" at the most.

The bridge was rated for its current condition using LFD. The resulting ratings were:

Operating Rating = 1.21, (without FWS allowance)
Inventory Rating = 2.02, (without FWS allowance)

Bearings: All bearings are steel high profile fixed or expansion bearings. They are in good condition overall (see photos 36 to 38). A few bearing locations have loose or missing anchor bolt nuts (see the Bottom of Deck Condition Survey for locations). The paint has failed on a number of bearings at the abutments due to the heavy amount of roadway drainage passing through the failed transverse deck joints located above. This has allowed minor corrosion to start on these bearings. No unusual tilting of the expansion bearings was noted during the inspection.

Substructure:

Abutments: The abutments are reinforced concrete spill through type with parallel wingwalls. They are in **satisfactory condition**. Damage noted to the abutments consisted of tight cracks in the caps and moderate amounts of delaminated and spalled concrete. This damage was primarily noted at the north abutment. It is estimated that approximately 15 sq. ft. of concrete repair is currently required on the abutments (see photos 41 and 42).

Piers: The piers are reinforced concrete multi-column type. They are in **satisfactory condition**. The piers located beneath continuous deck locations exhibit little or no damage. Those located beneath the transverse deck joints, Piers 3, 8, and 13, have large amounts of concrete delaminations and spalls present. It is estimated that approximately 470 sq. ft. of concrete repair is currently required on the piers (see photos 43 to 50).

Slope Protection: Riprap has been placed at each end of the bridge and is in good condition. It covers the area beneath each end span, around the abutment wingwalls and around each first interior pier from each end of the bridge (see photos 5 and 41 to 43).

Inspection History (NBIS Ratings):

| <u>Year:</u> | <u>Deck:</u> | <u>Super:</u> | <u>Sub:</u> |
|--------------|--------------|---------------|-------------|
| 2010 | 5 | 6 | 6 |
| 2011 | 4 | 6 | 6 |
| 2012 | 4 | 6 | 6 |
| 2014 | 4 | 6 | 6 |

Geometric, Horizontal and Vertical Clearances:

The horizontal clear width through this structure matches the urban approach roadway cross section at the south end of the bridge.

This structure crosses a road and a double track rail line. The minimum vertical clearances to these are as follows:

| | |
|----------------|--------|
| Reed Road = | 14.70' |
| UP Rail Line = | 22.77' |

IV. Potential Scope of Work Determination and Analysis:

The following potential scopes of work were considered for this structure:

Scope of Work-A: Rehabilitation-Deck Repair and Overlay

For this scope of work the existing deck would be repaired and a new microsilica-concrete overlay placed on the deck. The major work items for this scope of work would include:

- Deck scarification using hydro-demolition
- Full depth deck repairs
- Microsilica concrete overlay of the deck
- New transverse deck joints at the abutments
- Concrete repairs to the parapets and raised median
- Lighting repairs
- Replace the existing bearings beneath the transverse deck joints with elastomeric bearings
- Concrete repairs to the substructure
- Deck drain extensions
- Painting the structural steel located beneath the transverse deck joints

This scope of work has an estimated service life of 12 years before major deck repairs are required again. This reduced service life for the overlay is based on the advanced age of the existing deck and estimated high chloride content of the remaining concrete. The estimated cost for this bridge work is \$2,873,000.

Scope of Work-B: Rehabilitation-Deck Replacement

For this scope of work the existing deck would be replaced with a new composite 8" deck. The major work items for this scope of work would include:

- Deck removal and replacement with an 8" composite deck
- Concrete repairs to the substructure
- Replace the existing bearings beneath the transverse deck joints with elastomeric bearings
- Painting the structural steel located beneath the transverse expansion deck joints
- New lighting

This scope of work has an estimated service life of 25 years before deck replacement is potentially required. The estimated cost for this bridge work is \$6,454,000.

The bridge was rated for this proposed condition using LFD. The resulting ratings were:

Operating Rating = 1.15, (with 50 psf FWS allowance)

Inventory Rating = 1.92, (with 50 psf FWS allowance)

Scope of Work-C: Structure Replacement

The scope of work for this option would be to remove the existing structure and replace it with two separate single-span structures. The major work items for this scope would include:

- Two new single-span bridge structures of sufficient width to support an additional lane of traffic in each direction with a widened median and a shared-use path. One structure will be over the Union Pacific Railroad and the other over Reed Road.
- MSE wall to be constructed to “close off” the other existing spans.
- Shared-use path along Kirk Road between Cherry Lane and IL-38.
- New lighting.
- New culvert for White’s Creek through the MSE wall.


This scope of work has an estimated design life of 75 years. The estimated cost for this bridge work is \$19,500,000.

V. Discussion and Recommended Scope of Work:

Kane County has identified Kirk Road in its Strategic Plan to be widened to three lanes in each direction. Kane County, the Kane County Forest Preserve, and other agencies also expressed the need to connect the shared-use path along Kirk Road between IL 38 and Fabyan Parkway. Since the existing structure would not be able to accommodate the future roadway widening requirements, rehabilitation options were ruled out. Therefore, **Scope of Work-C: Structure Replacement** is recommended as the preferred alternative.

The bridge over the Union Pacific Railroad will span approximately 115' to 125'. The bridge over Reed Road will span approximately 70' to 80'. The clearance over the railroad will be increased to achieve a minimum 23'-0" clearance. The clearance over Reed Road will be increased to 14'-9" minimum, in accordance with the Bureau of Local Roads Manual.


Three mechanically stabilized earth (MSE) retaining walls will be constructed to support new fill. The southernmost wall will be “U” shaped. This wall will parallel Kirk Road and will support the south abutment of the bridge over the railroad. The middle wall will be box shaped. It will parallel Kirk Road between the railroad and Reed Road and will support the north abutment on the railroad bridge and the south abutment of the Reed Road Bridge. The northernmost wall will be “U” shaped and parallel Kirk Road and will support the north abutment of the Reed Road Bridge. A schematic sketch of the bridge and wall layout can be found in Figure 1.0. The wall lengths will be further defined during the TS&L development.



ATTACHMENTS:

- Attachment A. Roadway Classification Map**
- Attachment B. IDOT Master Structure Report**
- Attachment C. Bridge Inspection Report**
- Attachment D. Top and Bottom of Deck Condition Surveys**
- Attachment E. Substructure Condition Surveys**
- Attachment F. Cost Estimates**
- Attachment G. Proposed Structure**
- Attachment H. Staging Sketch**
- Attachment I. Structure Photographs**
- Attachment J. Existing and Proposed Roadway Cross Sections**
- Attachment K. Abbreviated Existing Plans**

ATTACHMENT A
ROADWAY CLASSIFICATION MAP



KIRK ROAD OVER THE UNION PACIFIC RAILROAD
ROADWAY CLASSIFICATION MAP

KANE COUNTY, ILLINOIS



ATTACHMENT A

ATTACHMENT B
IDOT MASTER STRUCTURE REPORT

Structure Number: 045-3096 District: 1

Data Related to Inspection Information

***Inspection Intervals ***
 Routine NBIS: 24 MOS Underwater: 0 MOS One Truck At A Time: 0 Tons
 Fracture Critical: 0 MOS Special: N Tons
 Bridge Posting Level: 5 No Posting Required

Inspection/Appraisal Information

Inspection Date: 05/17/2012 Inspection Temperature: 64 Deg. F Insp by (Name): C.C.SCHRAMM/HLR 2
 Deck: 4 POOR CONDITION - ADVANCED DETERIORATION Insp by (Name):
 Superstructure: 6 SATISFACTORY CONDITION - MINOR DETERIORATION Utilities Attached: 9 ELECTRIC
 Substructure: 6 SATISFACTORY CONDITION - MINOR DETERIORATION N N/A
 Culvert: N NOT APPLICABLE N N/A
 Channel and Protection: N NOT APPLICABLE F MICRO SIL CON OVRLY
 Structural Evaluation: 6 EQUAL TO PRESENT MINIMUM CRITERIA F NONE
 Deck Geometry: 5 BETTER THAN ADEQUATE TO BE LEFT IN PLACE J NONE
 Underclearance-Vert/Lat.: 9 SUPERIOR TO PRESENT DESIRABLE CRITERIA 7.5
 Waterway Adequacy: N NOT APPLICABLE
 Approach Roadway Align: 8 EQUAL TO PRESENT DESIRABLE CRITERIA
 Bridge Railing Appraisal: 2 Doesn't Meet Standards
 Approach Guardrail: 333 Acceptable Acceptable
 Pier Navig Protection: N N/A

*** Actual Posted Limits **
 Single Unit Vehicles: Tons
 Combination Type 3S-1: Tons
 Combination Type 3S-2: Tons
 One Truck At A Time: 0
 Last Paint Type:

Deck Wearing Surf:
 Deck Membrane:
 Deck Protection:
 Total Deck Thickness:
 Last Paint Date:
 Inspection Remarks:
 OVERLAY HEAVILY MAP CRACKED WITH NUMEROUS OPEN CRACKS, APPROX. 22.5% OF DECK SU RFACE IS DELAMINATED, MANY AREAS WITH CRACKS, LEACHING, DELAMINATIONS AND SPALL S ON UNDERSIDE OF DECK.

Underwater Inspection/Appraisal Information

Inspection Date: Inspection Method: Appraisal Rating:
 Temperature: Inspected By:
 Inspected By: Appraisal Rating:
 Inspection Remarks:

Scour Critical Information

Rating: Evaluation Method: Analysis By:
 Analysis Date: Fracture Critical Members: No
 Microfilm Data Recorded: No

Construction Information

Year: 1974 Original Reconstructed
 Route: FAS1100 Sta: 13+50.11
 Section Nbr: 192-3VB
 Contract Nbr:
 Fed Aid Pr #: SU 1100(101)
 Built By: 3 COUNTY AGENCY

Proposed Improvement

Cost Estimate Year: Length: *** Costs in Dollars ***
 Type of Work: Bridge Cost:
 Done By: Roadway Cost:
 Remarks: Total Project Cost:

ATTACHMENT C
BRIDGE INSPECTION REPORT



| | | | | | | |
|--|--------------------------|--------------------|------------------------------------|-----------------------|--------------|--------------|
| SN: 045-3096 | District: 1 | Spans: 18 | Appr. Spans: | Skew: 90 | ADT: 26,000 | Truck Pct: 7 |
| ADT Un: | Maint. Co: Kane | Twsp: Geneva | | Status: | | |
| Facility Carried: Kirk Road, FAU Rt. 2 | | | Feature Crossed: UP RR & Reeds Rd. | | | |
| Location: 0.2 MI S of IL-38 | | Municipality: | | Team/Sub Section: / | | |
| Bridge Name: | | | Material & Type: 4 / 2 | | | |
| Insp. Intervals Routine: | | Fracture Critical: | Underwater: | Special: | | |
| 90- Inspection Date: | 01 / 16 / 2014 | 90C- Temp. (°F): | 35 | 90A- Program Manager: | Mike Zakosek | |
| Is Delinquent: | <input type="checkbox"/> | Reason: | | | | |
| 90A1- Team Leader: | Mike Cima | 90A2- Inspector: | Ted Alleni | | | |

90B- Inspection Remarks:

Previous Inspection Overlay heavily map cracked, approx 22% of deck surface is delaminated or spalled. Underside of deck has many areas with cracks, leaching, delaminations and spalls.

| Resources | | | | | | | | | | |
|------------------------|-----------|----------|------------------|-------------------|-----------|-----------|---------------|-----------|----------|-------------------|
| Time to Inspect (H:M): | __ : __ | 7 : 0 | Traffic Control: | <u>Y</u> <u>Y</u> | Boat: | <u> </u> | Waders: | <u> </u> | Snooper: | <u>Y</u> <u>Y</u> |
| Ladder: | <u> </u> | Manlift: | <u> </u> | Bucket Truck: | <u> </u> | Other: | <u> </u> | | | |

| Inspector's Appraisals | | | |
|------------------------------|----------|-----|---|
| | Prev | New | Comments |
| 58 - Deck Condition: | <u>4</u> | 4 | Between 10-25% of the deck surface has delams/spalls present. |
| 59 - Superstructure Cond: | <u>6</u> | 6 | Steel girders have minor section loss in non-critical areas |
| 60 - Substructure Cond: | <u>6</u> | 6 | Moderate levels of delams/spalls present on Piers 3, 8 & 13 |
| 62 - Culvert Condition: | <u>N</u> | N | |
| 61 - Channel Condition: | <u>N</u> | N | |
| 71 - Waterway Adequacy: | <u>N</u> | N | |
| 72 - Approach Rdwy Align: | <u>8</u> | 8 | |
| 111 - Pier Navig Protection: | <u>N</u> | N | |

90B - Inspection Remarks:

The transverse joint seals at both abutments have failed. The top of deck is heavily delaminated & cracked with a large number of patches present. The bottom of the deck has numerous spalls and delaminations present. The steel beams have minor section loss near the transverse deck joints in non-critical areas. The piers located beneath the

Routine Inspection Report

Structure Number: 045-3096

Additional Inspection Data

| | | | | | | | | | | | | | | | | | | | |
|--------------------------------|------|-----|---|---|--|------|-----|---|---|------------------|------|-----|---|---|-------------|------|-----|---|---|
| 36A – Bridge Railing Adequacy: | Prev | New | 2 | 2 | Rail Types: GM Concrete Parapet w/aluminum railing | | | | | | | | | | | | | | |
| Approach Guardrail Adequacy: | Prev | New | 3 | 3 | 36B – Transitions: | Prev | New | 3 | 3 | 36C – Guardrail: | Prev | New | 3 | 3 | 36D – Ends: | Prev | New | 3 | 3 |

| | | | | | | | | | | | | | | |
|------------------------------------|------|-----|-----|-----|--------------------------|------|-----|---|---|-------------------------|------|-----|---|---|
| 108A – Wearing Surface Type: | Prev | New | F | F | 108B – Type of Membrane: | Prev | New | E | F | 108C – Deck Protection: | Prev | New | J | J |
| 108D – Total Deck Thickness (In.): | Prev | New | 7.5 | 7.5 | | | | | | | | | | |

| | | | | |
|---------------------------|------|-----|-----------|-----------|
| 59A – Paint Date (Mo/Yr): | Prev | New | 01 / 2003 | 01 / 2003 |
|---------------------------|------|-----|-----------|-----------|

| | | | | |
|-------------------|------|-----|---------|---------|
| 59B – Paint Type: | Prev | New | - - - - | - - - - |
|-------------------|------|-----|---------|---------|

Color: Fascia – _____; Inter. – _____; Railing – _____

| | | | | |
|---------------------------|------|-----|-------|-------|
| 59C – Utilities Attached: | Prev | New | 9 N N | 9 N N |
|---------------------------|------|-----|-------|-------|

| | | Prev | New | |
|-----------------------|---|------|-----|------|
| Weight Limit Posting: | 70A2 – Single Unit Vehicles: | — | | Tons |
| | 70B2 – Combination Type 3S-1 (3 or 4 axles): | — | | Tons |
| | 70C2 – Combination Type 3S-2 (5 or more axles): | — | | Tons |
| | 70D2 – One Truck at a Time: | — | | |

Joint Openings (In.): _____



90B – Inspection Remarks Continued:

transverse deck joints have numerous spalls and delams present. The piers not located below joints show little damage. The bridge approach slab at the north end has large open transverse cracks present. See the Bridge Inspection Narrative report for addition details.


| | Signature | Date |
|-----------------------------|------------------------|--------------|
| Inspection Team Leader: | <i>Michael D. Cava</i> | 2 / 3 / 2014 |
| Consultant Program Manager: | | / / |
| Agency Program Manager: | | / / |

ATTACHMENT D


TOP AND BOTTOM OF DECK CONDITION SURVEYS



WEST ELEVATION




PLAN



TYPICAL BRIDGE DECK CROSS SECTION
(Looking North)



LEGEND

- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | Delamination |
| DL = Delamination | Spalls |
| LE = Leaching | Crack |
| PD = Plugged Drain Hole | OC = Oil & Chip Patch |
| PS = Prestressed Strand | Concrete Patch |
| RF = Reinforcement | |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |



LOCATION SKETCH

GENERAL PLAN AND ELEVATION
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096





LEGEND

- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |


Note:
Damage area dimensions are shown as
length along beam x width across beam.

TOP/BOTTOM DECK SPANS 4-6
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096

PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14



SPANS 7-9
(Top View)



SPANS 7-9
(Bottom View)



LEGEND

- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | Delamination |
| DL = Delamination | Spalls |
| LE = Leaching | Crack |
| PD = Plugged Drain Hole | OC = Oil & Chip Patch |
| PS = Prestressed Strand | Concrete Patch |
| RF = Reinforcement | |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

Note:
Damage area dimensions are shown as length along beam x width across beam.

Minor damage to interior top and bottom flanges of fascia beams is common at drain locations (+5-10% loss max). Many drains do not extend 6" or more beyond the low steel elevation as desired.

TOP/BOTTOM DECK SPANS 7-9
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096






LEGEND

- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | Delamination |
| DL = Delamination | Spalls |
| LE = Leaching | Crack |
| PD = Plugged Drain Hole | OC = Oil & Chip Patch |
| PS = Prestressed Strand | Concrete Patch |
| RF = Reinforcement | |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

Note:
Damage area dimensions are shown as
length along beam x width across beam.

TOP/BOTTOM DECK SPANS 10-12
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096

PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14



SPANS 13-15
(Top View)

SPANS 13-15
(Bottom View)


LEGEND

- CO = Crack - Open
- CC = Crack - Closed
- CO = Corrosion
- DL = Delamination
- LE = Leaching
- PD = Plugged Drain Hole
- PS = Prestressed Strand
- RF = Reinforcement
- RP = Repair
- RS = Rust Staining
- SP = Spall
- SS = Shear Stirrup
- SP = Stalactites
- SS = Water Leakage
- Delamination
- Spalls
- Crack
- OC = Oil & Chip Patch
- Concrete Patch


Note:
Damage area dimensions are shown as
length along beam x width across beam.

TOP/BOTTOM DECK SPANS 13-15
 KIRK ROAD OVER UNION PACIFIC
 RAILROAD AND REED ROAD
 KANE COUNTY
 STRUCTURE NO. 045-3096

PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14



SPANS 16-18
(Top View)



SPANS 16-18
(Bottom View)

LEGEND


- CO = Crack - Open
- CC = Crack - Closed
- CO = Corrosion
- DL = Delamination
- LE = Leaching
- PD = Plugged Drain Hole
- PS = Prestressed Strand
- RF = Reinforcement
- RP = Repair
- RS = Rust Staining
- SP = Spall
- SS = Shear Stirrup
- SP = Stalactites
- SS = Water Leakage
- Delamination
- Spalls
- Crack
- OC = Oil & Chip Patch
- Concrete Patch

Note:
Damage area dimensions are shown as length along beam x width across beam.


Moderate Flaking with small spalls common full length of interior concrete construction joints. Estimate 25% of area delaminate 1' wide over full length of deck.

TOP/BOTTOM DECK SPANS 16-18
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


ATTACHMENT E
SUBSTRUCTURE CONDITION SURVEYS




ELEVATION
(Looking West @ Wingwall)




ELEVATION - S. ABUT.
(Looking South)




ELEVATION
(Looking East @ Wingwall)



ELEVATION
(Looking East @ Wingwall)



ELEVATION - N. ABUT.
(Looking North)




ELEVATION
(Looking West @ Wingwall)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

ABUTMENTS
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 1
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)








END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|---|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination |  Delamination |
| LE = Leaching |  Spalls |
| PD = Plugged Drain Hole |  Crack |
| PS = Prestressed Strand |  OC = Oil & Chip Patch |
| RF = Reinforcement |  Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 2
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




TOP PLAN




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | Delamination |
| DL = Delamination | Spalls |
| LE = Leaching | Crack |
| PD = Plugged Drain Hole | OC = Oil & Chip Patch |
| PS = Prestressed Strand | Concrete Patch |
| RF = Reinforcement | |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 3
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)








END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|---|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination |  Delamination |
| LE = Leaching |  Spalls |
| PD = Plugged Drain Hole |  Crack |
| PS = Prestressed Strand |  OC = Oil & Chip Patch |
| RF = Reinforcement |  Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 4
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 5
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 6
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 7
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14



TOP PLAN




END VIEW




ELEVATION

(Looking South)



END VIEW



ELEVATION


(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 8
 KIRK ROAD OVER UNION PACIFIC
 RAILROAD AND REED ROAD
 KANE COUNTY
 STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)








END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|---|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination |  Delamination |
| LE = Leaching |  Spalls |
| PD = Plugged Drain Hole |  Crack |
| PS = Prestressed Strand |  OC = Oil & Chip Patch |
| RF = Reinforcement |  Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 9
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 10
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW




ELEVATION
(Looking South)




END VIEW



END VIEW



ELEVATION
(Looking North)




END VIEW

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER II
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)








END VIEW




ELEVATION
(Looking North)

LEGEND

- | | |
|-------------------------|---|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination |  Delamination |
| LE = Leaching |  Spalls |
| PD = Plugged Drain Hole |  Crack |
| PS = Prestressed Strand |  OC = Oil & Chip Patch |
| RF = Reinforcement |  Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |


PIER 12
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096

PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14



END VIEW

ELEVATION
(Looking South)



END VIEW


ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | Delamination |
| DL = Delamination | Spalls |
| LE = Leaching | Crack |
| PD = Plugged Drain Hole | OC = Oil & Chip Patch |
| PS = Prestressed Strand | Concrete Patch |
| RF = Reinforcement | |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 13
 KIRK ROAD OVER UNION PACIFIC
 RAILROAD AND REED ROAD
 KANE COUNTY
 STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 14
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 15
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)








END VIEW




ELEVATION
(Looking North)

LEGEND


- | | |
|-------------------------|---|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination |  Delamination |
| LE = Leaching |  Spalls |
| PD = Plugged Drain Hole |  Crack |
| PS = Prestressed Strand |  OC = Oil & Chip Patch |
| RF = Reinforcement |  Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 16
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096


PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14




END VIEW



ELEVATION
(Looking South)



END VIEW



ELEVATION
(Looking North)

LEGEND

- | | |
|-------------------------|-----------------------|
| CO = Crack - Open | SP = Stalactites |
| CC = Crack - Closed | SS = Water Leakage |
| CO = Corrosion | |
| DL = Delamination | Delamination |
| LE = Leaching | Spalls |
| PD = Plugged Drain Hole | Crack |
| PS = Prestressed Strand | OC = Oil & Chip Patch |
| RF = Reinforcement | Concrete Patch |
| RP = Repair | |
| RS = Rust Staining | |
| SP = Spall | |
| SS = Shear Stirrup | |

PIER 17
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096

PROJECT NUMBER: 13.0342 | DRAWN: D.A.B. | DATE: 04/01/14

ATTACHMENT F
COST ESTIMATES

OPINION OF PROBABLE CONSTRUCTION COST

Computed: **MDC**
 Struct. No.: **045-3096**
 Location: **Kirk Rd over UP RR**

County: Kane
 Date: 4/21/2014

SCOPE OF WORK-A: Deck Repair and Overlay

| <u>Item</u> | <u>Unit</u> | <u>Quantity</u> | <u>Unit Price</u> | <u>Total</u> |
|--|-------------|-----------------|-------------------|-----------------------|
| Concrete Super Structure: | cu yd | 19 | \$1,200.00 | \$22,800.00 |
| Reinf. Bars, (Epoxy Coated): | lb | 4900 | \$1.50 | \$7,350.00 |
| Bridge Deck Grooving: | sq yd | 7875 | \$5.00 | \$39,375.00 |
| Protective Coat: | sq yd | 10193 | \$2.00 | \$20,386.00 |
| Elastomeric Bearing, Type-1: | each | 10 | \$900.00 | \$9,000.00 |
| Elastomeric Bearing, Type-2: | each | 70 | \$1,200.00 | \$84,000.00 |
| Strip Seal Expansion Joint: | ft | 124 | \$200.00 | \$24,800.00 |
| Traffic Barrier Terminal, Type 5: | each | 2 | \$1,000.00 | \$2,000.00 |
| Traffic Barrier Terminal, Type 6: | each | 2 | \$3,000.00 | \$6,000.00 |
| Steel End Sections-Guardrail: | each | 4 | \$3,000.00 | \$12,000.00 |
| Steel Plate Beam Guardrail: | ft | 400 | \$32.00 | \$12,800.00 |
| Lighting Repairs | LS | 1 | \$25,000.00 | \$25,000.00 |
| Floor Drain Extensions: | each | 140 | \$225.00 | \$31,500.00 |
| Concrete Removal (special): | cu yd | 19 | \$1,500.00 | \$28,500.00 |
| Erosion Control | LS | 1 | \$8,000.00 | \$8,000.00 |
| Temp. Concrete Barrier (w/relocation): | ft | 1500 | \$38.00 | \$57,000.00 |
| Traffic Control and Protection | LS | 1 | \$45,000.00 | \$45,000.00 |
| Guardrail Removal: | ft | 150 | \$10.00 | \$1,500.00 |
| Clean & Paint Steel: | LS | 1 | \$60,000.00 | \$60,000.00 |
| Bridge Deck Hydro/Mech Scarification: | sq yd | 8490 | \$40.00 | \$339,600.00 |
| Bridge Deck Microsilica Conc. Overlay: | sq yd | 8490 | \$80.00 | \$679,200.00 |
| Deck Slab Repair (full depth): | sq yd | 761 | \$700.00 | \$532,700.00 |
| Concrete Repair-Parapet & Median: | sq yd | 360 | \$290.00 | \$104,400.00 |
| Epoxy Crack Sealing: | ft | 200 | \$45.00 | \$9,000.00 |
| Formed Concrete Repair <= 5": | sq ft | 500 | \$125.00 | \$62,500.00 |
| Jack & Remove Existing Bearing: | each | 80 | \$1,500.00 | \$120,000.00 |
| RR Protective Liability Insurance | LS | 1 | \$50,000.00 | \$50,000.00 |
| | each | 0 | \$50.00 | <u>\$0.00</u> |
| Sub-Total from above: | | | | \$2,394,411.00 |

Mob., Contingency & Other (20%): \$478,882.20

Total Estimated Cost = \$2,873,293

OPINION OF PROBABLE CONSTRUCTION COST



Computed: **MDC**
 Struct. No.: **045-3096**
 Location: **Kirk Rd over the UP RR**

County: Kane
 Date: 4/21/2014


SCOPE OF WORK-B: Deck Replacement

| <u>Item</u> | <u>Unit</u> | <u>Quantity</u> | <u>Unit Price</u> | <u>Total</u> |
|---|-------------|-----------------|-------------------|-----------------------|
| Stud Shear Connectors | each | 41280 | \$2.75 | \$113,520.00 |
| Concrete Super Structure: | cu yd | 2840 | \$1,000.00 | \$2,840,000.00 |
| Reinf. Bars, (Epoxy Coated): | lb | 737960 | \$1.25 | \$922,450.00 |
| Bridge Deck Grooving: | sq yd | 7951 | \$5.00 | \$39,755.00 |
| Protective Coat: | sq yd | 10404 | \$2.00 | \$20,808.00 |
| Elastomeric Bearing, Type-1: | each | 10 | \$900.00 | \$9,000.00 |
| Elastomeric Bearing, Type-2: | each | 70 | \$1,200.00 | \$84,000.00 |
| Strip Seal Expansion Joint: | ft | 124 | \$200.00 | \$24,800.00 |
| Finger Plate Expansion Joint | ft | 186 | \$1,900.00 | \$353,400.00 |
| Guardrail Removal: | ft | 150 | \$10.00 | \$1,500.00 |
| Traffic Barrier Terminal, Type 5: | each | 2 | \$1,000.00 | \$2,000.00 |
| Traffic Barrier Terminal, Type 6: | each | 2 | \$3,000.00 | \$6,000.00 |
| Steel End Sections-Guardrail: | each | 4 | \$3,000.00 | \$12,000.00 |
| Steel Plate Beam Guardrail: | ft | 400 | \$32.00 | \$12,800.00 |
| Light Pole w/Luminair, Bridge Mounted: | each | 10 | \$3,500.00 | \$35,000.00 |
| Floor Drains: | each | 150 | \$345.00 | \$51,750.00 |
| Drainage Scuppers, DS-11: | each | 16 | \$1,275.00 | \$20,400.00 |
| Deck Removal on steel bm-reuse bm: | cu yd | 2467 | \$150.00 | \$370,050.00 |
| Traffic Control and Protection | LS | 1 | \$60,000.00 | \$60,000.00 |
| Temp. Concrete Barrier (w/relocation): | ft | 1500 | \$38.00 | \$57,000.00 |
| Staging Traffic Control Prot & Signing: | LS | 1 | \$55,000.00 | \$55,000.00 |
| Clean & Paint Steel: | LS | 1 | \$60,000.00 | \$60,000.00 |
| Epoxy Crack Sealing: | ft | 200 | \$45.00 | \$9,000.00 |
| Formed Concrete Repair <= 5": | sq ft | 500 | \$125.00 | \$62,500.00 |
| Erosion Control | LS | 1 | \$10,000.00 | \$10,000.00 |
| Jack & Remove Existing Bearing: | each | 80 | \$1,200.00 | \$96,000.00 |
| RR Protective Liability Insurance | LS | 1 | \$50,000.00 | \$50,000.00 |
| | each | 0 | \$50.00 | <u>\$0.00</u> |
| Sub-Total from above: | | | | \$5,378,733.00 |
| Mob., Contingency & Other (20%): | | | | <u>\$1,075,746.60</u> |
| Total Estimated Cost = | | | | \$6,454,480 |


ATTACHMENT G
PROPOSED STRUCTURE



WEST ELEVATION




PLAN




TYPICAL BRIDGE DECK CROSS SECTION
(Looking South)

SCOPE OF WORK A & B


PROPOSED STRUCTURE
KIRK ROAD OVER UNION PACIFIC
RAILROAD AND REED ROAD
KANE COUNTY
STRUCTURE NO. 045-3096




ELEVATION



PLAN




PROPOSED TYPICAL SECTION - OVER UNION PACIFIC RAILROAD
(Looking North)



PROPOSED TYPICAL SECTION - OVER REED ROAD
(Looking North)

FILE NAME = SA\JUL\35800-35991\35807\003\Micro\CA00_Sheets\BGR_Exhibits\0453096-081234-BERI.dgn



1170 SOUTH HOUBOLT ROAD
JOLIET, ILLINOIS 60431
(815) 744-4200
IDFPR NO. 184-001273

| | | |
|--------------|------------|---------|
| USER NAME = | DESIGNED - | REVISED |
| CHECKED - | CHECKED - | REVISED |
| PLOT SCALE = | DRAWN - | REVISED |
| PLOT DATE = | CHECKED - | REVISED |

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**


**PROPOSED STRUCTURE
STRUCTURE NO. 045-3096**

SHEET NO. OF SHEETS


| F.A.P. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. |
|---------------------------|-----------------|--------|--------------|-----------|
| 360 | 12-000192-04-BR | KANE | | |
| CONTRACT NO. | | | | |
| ILLINOIS FED. AID PROJECT | | | | |

Scope of Work C

ATTACHMENT H
STAGING SKETCH




STAGE 1 TRAFFIC AND REMOVAL
(Looking North)




STAGE 2 TRAFFIC AND CONSTRUCTION
(Looking North)

SCOPE OF WORK A & B


STAGING SKETCH
KIRK ROAD OVER UNION PACIFIC RR & REED ROAD
FAU ROUTE 2
KANE COUNTY
SECTION 21-000192-04-BR
STRUCTURE NO. 045-3096



STAGE 1 TRAFFIC AND REMOVAL SECTION - TYPICAL
(Looking North)



STAGE 2 TRAFFIC AND CONSTRUCTION SECTION - KIRK ROAD OVER UNION PACIFIC RAILROAD
(Looking North)



STAGE 2 TRAFFIC AND CONSTRUCTION SECTION - KIRK ROAD OVER REED ROAD
(Looking North)

FILE NAME = SA\JOL\35800-35991\35807\003\Micro\CA00_Sheets\BCR_Exhibits\0453096-081234-BCR2.dgn

Scope of Work C

SA
STRAND
ASSOCIATES

1170 SOUTH HOUBOLT ROAD
JOLIET, ILLINOIS 60431
(815) 744-4200
IDFPR NO. 184-001273

USER NAME =
DESIGNED -
CHECKED -
PLOT SCALE =
DRAWN -
PLOT DATE =
CHECKED -

DESIGNED -
CHECKED -
DRAWN -
CHECKED -

REVISED
REVISED
REVISED
REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

STAGING SKETCH
STRUCTURE NO. 045-3096

SHEET NO. OF SHEETS

| F.A.P. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. |
|---------------------------|-----------------|--------|--------------|-----------|
| 360 | 12-000192-04-BR | KANE | | |
| CONTRACT NO. | | | | |
| ILLINOIS FED. AID PROJECT | | | | |

ATTACHMENT I
STRUCTURE PHOTOGRAPHS



Photo No. 1
Looking south through bridge



Photo No. 2
Looking north through bridge



Photo No. 3
Looking east from bridge (2012 photo)



Photo No. 4
Looking west from bridge (2012 photo)



Photo No. 5
East elevation of bridge



Photo No. 6
West elevation of bridge



Photo No. 7
North approach pavement looking east



Photo No. 8
South approach pavement looking east



Photo No. 9
North abutment transverse joint, seal is leaking




Photo No. 10
Pier 3 transverse joint



Photo No. 11
Pier 8 transverse joint




Photo No. 12
Pier 13 transverse joint



Photo No. 13
South abutment transverse joint, seal has failed




Photo No. 14
West parapet looking south



Photo No. 15
East parapet looking northeast



Photo No. 16
Delaminated concrete on parapet - common



Photo No. 17
Spalled concrete on parapet - common



Photo No. 18
Top of deck, span 5 SB, looking south



Photo No. 19
Top of deck, span 5 SB – intersecting open cracks in overlay (common)



Photo No. 20
Top of deck, span 9 SB, looking south



Photo No. 21
Top of deck, span 9 SB – open cracks in overlay (common)



Photo No. 22
Top of deck, span 16 SB - spall



Photo No. 23
Top of deck, span-8 NB, looking north



Photo No. 24
Top of deck, span-7 NB, oil and chip patch



Photo No. 25
Top of deck, span-7 NB, damaged concrete patch



Photo No. 26
Top of deck, span-3 – intersecting open cracks in overlay



Photo No. 27
Missing light pole, span-14, west side



Photo No. 28
West deck fascia – typical condition, looking SW



Photo No. 29
Bottom of deck and beams, span-4 – center bays, looking south



Photo No. 30
Bottom of deck and beams, span-8 – center bays, looking south



Photo No. 31
Bottom of deck and beams, span-15 – center bays, looking south



Photo No. 32
Bottom of deck and beams, span-16 – center bays, looking south



Photo No. 33
Fascia bay - typical



Photo No. 34
Bottom of deck and beams, span-13, looking north




Photo No. 35
Beams and deck, span-10, looking NE



Photo No. 36
Expansion bearing at north abutment – typical condition



Photo No. 37
Expansion bearings at Pier-3, typical condition beneath interior transverse joints



Photo No. 38
Expansion bearing at Pier-5, typical condition beneath continuous deck locations



Photo No. 39
Corrosion on web and bottom flange on Beam-6 from west side near Pier 3




Photo No. 40
Typical pitting of web near Pier-13



Photo No. 41
Abutment cap – typical condition



Photo No. 42
NE abutment wingwall



Photo No. 43
Pier 1, looking SW



Photo No. 44
Pier 3, looking SE



Photo No. 45
Pier 3, looking SW, cracking and delaminations common in cap



Photo No. 46
Pier 7, looking south (typical pier condition without transverse deck joint)



Photo No. 47
Pier 8, looking south



Photo No. 48
Pier 8, delaminations at top of west column, looking SW




Photo No. 49
Pier 13, looking south



Photo No. 50
Pier 13, east end looking south, spalling and delaminations common in cap


ATTACHMENT J

EXISTING AND PROPOSED ROADWAY CROSS SECTIONS



EXISTING ROADWAY CROSS SECTION
 (Looking South)

EXISTING & PROPOSED CROSS SECTIONS
 KIRK ROAD OVER UNION PACIFIC RR & REED ROAD
 FAU ROUTE 2
 KANE COUNTY
 SECTION 21-000192-04-BR
 STRUCTURE NO. 045-3096



FILE NAME = SA\JOL\3500-3599\3507\003\Micro\CA00_Sheets\BGR Exhibits\0453096-081234-BGR3.dgn

SA
STRAND
ASSOCIATES

1170 SOUTH HOUBOLT ROAD
JOLIET, ILLINOIS 60431
(815) 744-4200
IDFPR NO. 184-001273

| | | |
|--------------|------------|---------|
| USER NAME = | DESIGNED - | REVISED |
| | CHECKED - | REVISED |
| PLOT SCALE = | DRAWN - | REVISED |
| PLOT DATE = | CHECKED - | REVISED |

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

PROPOSED ROADWAY CROSS SECTIONS
STRUCTURE NO. 045-3096

SHEET NO. OF SHEETS

| F.A.P. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. |
|---------------------------|-----------------|--------|--------------|-----------|
| 360 | 12-000192-04-BR | KANE | | |
| CONTRACT NO. | | | | |
| ILLINOIS FED. AID PROJECT | | | | |

ATTACHMENT K
ABBREVIATED EXISTING PLANS

